The Alaska Karlroad 77.72

SEP 4 1935

General Manager

Anchorage, Alaska, August 30th, 1935.

Colonel Ohlson:

In connection with AX Report 38 covering damage to Flat Car 722 in Extra 801 south August 22nd, this train had 92 cars. Proper test of the air brakes was made at Anchorage and indicated no quick action brakes. Train departed from Anchorage and it was not necessary to use the air brakes until the train commenced to decend Potter Creek Hill when an application of the air brakes was made at which time a reduction of five pounds was made in the train line. Immediately this reduction was made train went into emergency application causing damage as stated in AX Report 38.

Effort was made to locate the car that caused the emergency application but it could not be found at that time. After reducing at Potter, train proceeded and in stopping at Indian and again at Bird train went into emergency application. Test was further made to endeavor to detect the car causing the emergency applications several cars being cut out. Finally Car 2265 was cut out which corrected the condition. Emergency application was not caused by Car 1503.

Attached is Mr. Kinsell's report covering.

JTC: K

T. Cunningham,
(Sup't. of Transportation

.

## Reproduced at the National Archives at Anchorage

MAR 15 1941

Pile 88...0

WAR 15 1941

Pile 88...0

File 88...0

File 88...0

File 88...0

File 88...0

File 88...0

File 88...0

lest might March 14th, 8:40 p.m., Extra 801 Bouth, pase of through tunnel 48.5 a timber fell down from the roof of the tunnel and a mak whistle waive on this engine breaking it off, resulting in engine dying on main track in this tunnel. It was necessary to run Magine 70% from Seward to Lile 48.8 to tick up this twain and handle to Leward.

I understand there has been timber falling out of the roof of this tunnel on different occasions.

It was also reported this morning that each time that engine passes over the sour end of Bridge 48.3 bridge settles about ten inches.

Solver of Bring 3 mg.

3 %. Sunninghou

Supit. of Wrensportedion

Anchorage, Alaska, March 10, 1932.

File No. 581.

Col. Ohlson:

Following report from Caretaker Peck at Wasilla:

\*Southbound Extra 606 South Conductor Brennan struck dog team in cut between section house and ice siding killed two dogs demolished sled scattered farm produce Harry Sears and wife narrowly escaped believe impossible that trainmen to see ahead account throwing drift and strong wind."

Above for your information.

The Alaska Railroad REC. IVEN

MAR 11 1932

OFFICE OF

General Manager

T. Cunningham,

t. of Transportation.

JTC:W