DI-103 (Approved April 1942)

UNITED STATES DEPARTMENT OF THE INTERIOR Report No.

The Alaska Railroad (Service)

REPORT OF SURVEY

To Members of Board of Survey		Anchorage (Location)
(Luke R. Lamb, Reino Vanaja, You are requested to convene	Leif Strand,	(Location)

for the purpose of surveying the unserviceable (or) lost, stolen, damaged property listed below.

PROPERTY No. ARTICLES QUANTITY VALUE A B 23 Consolidation Oil 2-8-0 Locomotive 1 \$8.558	DSITION*
1 23 Consolidation 011 2-8-0 Locomotive 1 \$8,558 Free to ARR Above represents	C D
Consolidation fil 2-8-0 Locemotive 1 \$8,558 Free to ARR Above represents	
Consolidation 011 2-8-0 Locomotive 1 \$8,558 Free to ARR Above represents	
Consolidation Oil 2-8-0 Locemotive 1 \$8,558 Free to ARR Above represents	
Above represents	37g CD4
Above represents	
represents	
Located at Anchorage Yards: (See Jack M. Karterman for definite	Andrew Co.
location	
	<i>(</i>
2 115 1 qt. carbon tet fire artinguishers 115 No longer services	ble
3 22 gal. chemical extinguisher 3 No longer services	hle
and the second of the second o	
The second of th	100
green which is the property of the state of the property of the state	7.12
The second of the Tables and the second second of the seco	altal lating
	TOPA STATE
	2.4
	القائل يبدي
	10 3
	3/ 3//24
The company of the control of the co	A AME

<sup>To be filled in by Board:
(A) Continued in service.
(B) To be destroyed.</sup>

⁽C) Advertised for sale. See Executive Order No. 6166, June 10, 1933

(TO BE COMPLETED ON SURVEY OF LOST, STOLEN, OR DAMAGED PROPERTY)

DATE AND CIRCUMSTANC	ES:			
The property of the second sec	- n '1	7. 1780 -0	7- 1	7 194

6 . List in 190	7.	
FINDINGS: Boder in very poor	condition fints	rial bod. od od
Throttle value leading	bally	
, Broken and patched in	give frame	
Broken and patchel en	plender	
Only engine on sys	Well-representation of the second sec	
value gove therefore parts for	it not on han	a ·
RECOMMENDATIONS:*		
for the above re	issons I won	td alcommind
Engine 23 be disposed of		
bell and other parts the	t can be me	on other
enganes:		
Marie Marie Marie Marie	S was well much a fight	Det.
(Approving Officer)	Board Members	Date of Appointment
Date Title	Keins Vanaja	
A DESCRIPTION OF THE PARTY OF T	Leve R. Lam	L apr 194
Date recorded(Prop. Section) (Accts. Section)	1 aucres	1 Spil 7, 19d
	Teil Shami	The state of the

(TO BE COMPLETED ON SURVEY OF UNSERVICEABLE PROPERTY)

Tiens 2+3

We certify that the property listed on the first page of this report has been inspected by us and recommend disposition be made thereof as indicated. We further certify that items recommended for destruction have been destroyed in our presence.

(Approving Officer)	Board Members	Date of Appointment
Date Title	Lupe K. Samp	4-7-47
Date recorded(Prop. Section) (Accts. Section)	Paulsties	4-7-47
to patient with the first and a superior and the superior anamed and the superior and the superior and the superior and the s	Leig Strang	4-7-47

*Should include recommendation for collection from responsible employee(s) or release from lightlity. Note.—Sheets of paper, properly captioned, may be used and securely attached to report where space is not sufficient.

403

Anchorage - April 15, 1947

in. C. A. Dividict:

This is your authority to scrap Consolidation Cil 2-8-C Locanotive No. 23. Original value \$8,558, which represents mechanical charges for putting this engine in operation as it was a donation from the Copper River Northwestern Bailway. Scrap value \$500.

DC: MR. J. T. COMMINGRAM
MR. J. J. DELAWAY
MR. B. A. MEMBERSTROM
MR. EARL MAIN
MR. DOM RECELL
CAR SERVICE CLERK

(SIGNED) J. P. JOHNSON J. P. Johnson General Manager

Chainf