571

ADDRESS ONLY

THE ALASKA RAILROAD

## UNITED STATES DEPARTMENT OF THE INTERIOR THE ALASKA RAILROAD

HEALY ALASKA AUG. 14/1946.

MR.G.W.COLWELL, CHIEF ENGR. ANCHORAGE, ÅLASKA.

IN REGARDS TO THE ACCIDENT OF AUG.5TH AT HEALY, JOHN SZWABAWSKI THE CAT DRIVER WAS DOZING BETWEEN THE LEGS OF THE WYE.HE HAD BEEN INSTRUCTED BY THE SECTION FOREMAN MR.SPADERO ABOUT 2:00 P M THAT A TRAIN WAS DUE IN ABOUT 20 MINS.OR HALF AN HOUR, AND TO BE ON THE WATCH FOR IT AND NOT TO FOWL THE MAIN LINE.

PASSENGER EXTRA 557 CAME ALONG THIS POINT ABOUT 2:30. APPARENTLY THE CAT WAS BACKING UP ON AN ANGLE AND THE DOZER FRAME HIT THE AUTOMATIC LUBRICATOR ON ENG 557 AS IT WAS PASSING THIS POINT, ENGINEER BEBEE APPLIED EMERGENCY AIR COMING TO A STOP AT ONCE.

LUBRICATOR ON ENGINE WAS DAMAGED BEYOND REPAIR.

NO DAMAGE AT ALL TO THE CAT. CAT DRIVER CLAIMED HE DID NOT SEE THE ONCOMING TRAIN UNTIL IT WAS TOO LATE. THIS MAN WAS DISMISSED FROM THE DUTIES OF CAT DRIVER AND DOZER MAN AS HE HAD MISREPRESENTED HIMSELF. HE HAD BEEN SENT TO CLEAR FROM ANCHORAGE ABOUT JULY 3IST. AS AN OILER FOR THE DRAGLINE, WE ALREADY HAD AN OILER THERE, I WAS IN NEED OF A MAN AT HEALY, WHO COULD HANDLE A DOZER, SINCE HE ASSURED ME HE COULD HANDLE A DOZER, I SENT HIM TO HEALY AUG 3RD.ON THE WORK TRAIN, AND HE REPORTED TO SECTION FOREMAN SPADERO AS A CAT DRIVER.

J.P. MCNAVISH,
ROADMASTER

Anchorage, Alaska August 6, 1946

MR. J. W. STIDERSELL MR. A. M. COLUMN

Veference is made to AN No. 21, dated August 5, 1946, in which Train No. 4, Inside 557, struck bulldozer which was standing between legs of Nye just north of Healy breaking loft lubricator on Engine 557, delaying train 50 miguses.

Mill you arrange to make a complete investigation of this accident and advice what disciplinary action is meted out to the man responsible for leaving the bulldozer in a non-clearance position.

J. J. Johnson Comeral Manager